

The extent to which disabled pupils (including those with learning difficulties) can participate in the curriculum.

	<u>Targets</u>	<u>Strategies</u>	<u>Outcome</u>	<u>Timeframe</u>	<u>Goals ac</u>
Wheelchair users	Access to rooms	With the exception of our oldest	Achieved	Complete	Y
	Books & Equipment	Where a wheelchair users requires	Achieved	Complete	Y
Physical impairment	Mobilty to rooms	With the exception of our oldest	As needed	Complete	Y
	Books & Equipment	Where a student with mobility needs	As above	Complete	Y
Temporary impairment	Mobilty to rooms	With the exception of our oldest	As needed	Complete	Y

Making written information accessible in a range of different ways for disabled pupils, where it is provided for pupils who are not

	<u>Targets</u>	<u>Strategies</u>	<u>Outcome</u>	<u>Timeframe</u>	<u>Goals ac</u>
Dyslexia/Dyspraxia/Dyscalculia	Support	Assess for need	Resource	Ongoing	Resources to date
	Educational material	Assess for need	Resource	Ongoing	Resources to date
Autism/Aspergers Syndrome	Support	Assess for need	Resource	Ongoing	Resources to date
	Educational material	Assess for need	Resource	Ongoing	Resources to date
Irlen/Scotopic Sensitivity Syndrome	Support	Assess for need	Resource	Ongoing	Resources to date

Visual/Hearing impaired	Educational material	Assess for need	Resource	Ongoing	Resources to date
	Support	Assess for need	Resource	Ongoing	Resources to date
EAL	Educational material	Assess for need	Resource	Ongoing	Resources to date
	Support	Assess for need	Resource	Ongoing	Resources to date

PROPOSED DEVELOPMENTS IN IN PHYSICAL ACCESS TO EDUCATION AND ASSOCIATED SERVICES

CAR PARKING

	<u>Targets</u>	<u>Strategies</u>	<u>Outcome</u>	<u>Timeframe</u>	<u>Goals ac</u>
Disabled parking bays not signposted from entrance	Evident from start of car parking.	When renew sign.	Monitor	2/3 years	Bays clearly marked from entrance and kept free.
Disabled spaces not big enough for a wheelchair parked alongside	Provide 2 spaces with shared wheelchair access.	Designate 3 spaces. A communal centre space for wheelchair parking either side.	Better provision		Additional bays marked December 2015 + extra space. Complete New space has hashed wheelchair access.
Car park not adequately lit	Better illumination within planning consents + local objec.	Apply to Plan. Dept. for increased number of lights + deal with obj. from neighbours.	Better security & safety for staff, pupils & visitors.	2-3 yrs	Complete
No tactile signs from car park to buildings	Signs clear & understandable for visually impaired	Replace existing signs.	Aid to partially sighted.	1-2 yrs	Complete

EXTERNAL STEPS

<p>No visual or tactile warnings at top and bottom of steps</p> <ul style="list-style-type: none"> - Steps to Youngers x2 - Steps to DH Reception - External steps to Cellars - Steps to Dining Room - Steps to Schofield - Steps to PAC - Fire exit from Youngers - Steps rear of SH 	<p>Signs clear & understandable for visually impaired</p>	<p>Have yellow steps and blistered kerbing, along with appropriate handrails fitted in line with DDA guidelines</p>	<p>Aid to partially sighted.</p>	<p>1-2 yrs</p>	<p>Ongoing Quotations sought Added to maintenance for Easter holidays 201 repaint nosings</p>
<p>Inadequate lighting and badly positioned</p> <ul style="list-style-type: none"> - Steps to Dining Room - Entrance to DH Reception 	<p>Safer access</p>	<p>Audit & prioritise in future maintenance work.</p>	<p>Safer accessibility</p>	<p>1-3 yrs</p>	<p>Complete</p>
<p>Treads not long enough, nosing damaged & different lengths</p> <ul style="list-style-type: none"> - External steps to Cellars 	<p>Safer access</p>	<p>Audit & prioritise in future building work. Regular maintenance.</p>	<p>Safer accessibility</p>		<p>Complete</p>
<p>Risers not shallow enough and of different heights</p> <ul style="list-style-type: none"> - Steps to DH Reception - External steps to Cellars 	<p>Safer access</p>	<p>DH - audit & prioritise in future building work. Cellars - consider alternative access by mechanical means on internal cellar stairs.</p>	<p>Safer accessibility</p>	<p>2-5 yrs</p>	<p>Signed alternative access to DH from car park</p>

	<u>Targets</u>	<u>Strategies</u>	<u>Outcome</u>	<u>Timeframe</u>	<u>Goals achieved</u>
<p>Landings not big enough & at intermediate levels</p>	<p>Safer access</p>	<p>Covered by fire evacuation procedure. Audit & prioritise in any</p>	<p>Safer accessibility</p>	<p>Ongoing</p>	

- Fire exit from Youngers		changes to building.			
Entrance not clearly distinguishable - Rawcliffes exit	Safer access	Audit & prioritise in future maintenance work	Safer accessibility	1 - 5yrs	Quotes for changing ac Dower in progress -nev glass doors and new lo access ramp
Threshold not level or flush - DH Reception - East door DH - Rawcliffes exit	Greater accessibility	When replacing door will audit & prioritise	Easier access	1-5 yrs	DH - signed alternative from car park New ramp with relocat
Can people see each other through door - standing or sat - Rawcliffes exit	Greater accessibility	When replacing door will look at a glass panel	Easier access	1-5 yrs	New door will be half g reveal also glazed Rcliffes to have glass vi In door
Not enough space for wheelchair user to open door while clear of swing - DH Reception	Greater accessibility	Use of newly signed access from car park	Easier access		Complete
Door control not located clearly - All doors to Youngers - Rawcliffes exit DH	Greater accessibility	The current situation seems to be adequate and it will continue to be monitored. Visitors are always accompanied by a staff member who operates the door control	Easier access		Electronic lit door keyp all main Dowerexterna One hand operation (2
Door handle not easy to grip - DH Reception - Rawcliffes exit DH	Greater accessibility	DH - use of newly signed access from car park Raw exit - replace handles	Easier access Easier access		Complete Complete

	<u>Targets</u>	<u>Strategies</u>	<u>Outcome</u>	<u>Timeframe</u>	<u>Goals ac</u>
Entryphones & security systems not suitable for people with sensory or mobility impairments - Youngers x 2 - DH Reception - East Door DH	Greater accessibility	Monitor & when replace door - change	Easier access	2 -3 yrs	All doors fitted(2017) v entry - only require on Operation for entry an
Entrance not easy to distinguish - Fire Exit Watson	Greater accessibility	Covered by fire evac procedure & monitored to be changed in any building alteration	Easier access	2 - 5yrs	Complete
Door opening not wide enough - Fire Exit Watson	Greater accessibility	Covered by fire evac procedure & monitored to be changed in any building alteration	Easier access	2 - 5yrs	Complete
No level or flush threshold - Front entrance to DR - Fire Exit Watson	Greater accessibility	Alternative flush entrance a short distance away Wat - Monitored in any building alteration	Easier access	2 - 5yrs	Alternative level ent/e: available
People can't see each other through door standing or seated - Front entrance to DR - Fire Exit Watson	Greater accessibility	New door fitted 2011 door ie Winter Garden Wat - Monitored in any building alteration	Safer access	2 - 5yrs	Complete

	<u>Targets</u>	<u>Strategies</u>	<u>Outcome</u>	<u>Timeframe</u>	<u>Goals ac</u>
Door control not clearly located - Doors to PAC x 2 - SH top doors	Greater accessibility	New access systems fitted 2011	Easier access		Complete

RECEPTION AREAS

<p>No transitional lighting</p> <ul style="list-style-type: none"> - DH - PAC - Sports Hall 	<p>Better illumination within planning consent & local objections</p>	<p>Additional lighting has been fitted in 2011</p>	<p>Safer access</p>	<p>2 - 3 yrs</p>	<p>Complete</p>
<p>No signs located to convey info for people with sight impairments or wheelchair users</p> <ul style="list-style-type: none"> - DH - PAC Foyer 	<p>Greater accessibility</p>	<p>Monitor, review, prioritise & program over 5yr period</p>	<p>Easier access</p>	<p>1 - 5 yrs</p>	<p>Quotes sought for DDA compliant signage</p>
<p>No induction loop facility</p> <ul style="list-style-type: none"> - DH - PAC Foyer - Sports Hall 	<p>Improved facility</p>	<p>Review & prioritise and program over 5yr period</p>	<p>Better provision</p>	<p>1 - 5 yrs</p>	
<p>No tactile signs on how to reach other areas</p> <ul style="list-style-type: none"> - DH - Sports Hall 	<p>Greater accessibility</p>	<p>Monitor, review, prioritise & program over 5yr period</p>	<p>Easier access</p>	<p>1 - 5 yrs</p>	<p>Quotes sought for DDA compliant signage</p>

CORRIDORS/ENTRANCE LOBBIES

	<u>Targets</u>	<u>Strategies</u>	<u>Outcome</u>	<u>Timeframe</u>	<u>Goals ac</u>
Corridors not wide enough for a wheelchair and for other people to pass.	Greater accessibility	The Dower House is a victorian building which is protected under planning regulations and conservation. There is wheelchair access available within the main corridors to reception. Timetabling and planning would allow for study	Easier access	1 - 5 yrs	
Corridor in DH leading to fire exit No turning space for wheelchair users - DH corridors leading to main office - Corridor in DH leading to fire exit	Greater accessibility	Plan & consider in any change of use in areas of the school	Easier access	1 - 5yrs	
No visual clues to help orientation - 3 entrances to Youngers - DH entrance & corridor to office - DH corridor to fire exit - Entrance to Dining Room - Entrance to Watson	Greater accessibility	Monitor, review, prioritise & program over 5 yr period	Easier access	1 - 5 yrs	Quotes sought for DDA compliant signage
No clear visibility of direction or information signs from both standing or seated positions - Youngers entrances x 3	Greater accessibility	Monitor, review, prioritise & program over 5yr period	Easier access	1 - 5yrs	Quotes sought for DDA compliant signage

INTERNAL DOORS

Doors not distinguishable from surroundings - Youngers	Safer access	In future decorating work will audit & prioritise	Safer accessibility	1 - 5yrs	Quotes sought for DDA compliant signage
---	--------------	---	---------------------	----------	---

- DH - PAC toilets				
-----------------------	--	--	--	--

	<u>Targets</u>	<u>Strategies</u>	<u>Outcome</u>	<u>Timeframe</u>	<u>Goals ac</u>
- Viewing Gallery - Watson	Safer access	In future decorating work will audit & prioritise	Safer accessibility	1 - 5yrs	
People cannot see each other from both standing or seated positions through doors - DH - Twin doors into Dining Room - Entrance to theatre - PAC toilets	Greater accessibility	When replacing door will look at a glass panel. Replaced 2011	Easier access	1 - 5yrs Ongoing Ongoing Ongoing	Y Complete
Door controls not distinguishable from door - DH	Greater accessibility	The current situation seems to be adequate but will continue to monitor if this is acceptable	Easier access	Complete	New electronic lit keypad and exit fitted 2017
Doors not easily gripped or operated - DH	Greater accessibility	Replace handles	Easier access	1 - 5yrs	Complete
Space not adequate alongside leading edge for a wheelchair user or someone with limited mobility to reach door controls while clear of door swing - Viewing Gallery	Greater accessibility	Audit, prioritise & incorporate in future building plans	Easier access	1 - 5yrs	

INTERNAL RAMPS

Handrail not suitable by ramp (one side only) - Youngers - PAC	Greater accessibility	Audit, prioritise & incorporate in future building plans	Easier access	1 - 5yrs	Planter handrails added steps November 2016
---	-----------------------	--	---------------	----------	---

INTERNAL STAIRS/STEPS

	<u>Targets</u>	<u>Strategies</u>	<u>Outcome</u>	<u>Timeframe</u>	<u>Goals achieved</u>
Nosings not readily identifiable - DH main staircase	Safer accessibility	Due to the age of the building, planning and conservation permission will be required before alteration can be made to these stairs	Use alternate stairs with highlighted nosings	1-3 yrs	
Handrails not suitable on both sides - DH main staircase - DH staircase near D4 - Back staircase - Staircase leading to D26 - PAC - SH	Greater accessibility	Audit & prioritise in future building work	Safer movement around school	1 - 5yrs	On going
Landings not big enough - Back staircase - DH staircase near D4	Safer movement around school	Audit & prioritise in future building work	Safer movement around school	1 - 5yrs	Alternative access via main staircase
No visual warning at top of flight - Youngers - DH main staircase - DH staircase near D4 - Back staircase - Staircase leading to D26	Signs clear & understandable for all	Review, prioritise & program over 3yr period	Safer movement around school	2 - 3 yrs	Quotations requested

- To Science Labs. - PAC - SH - Watson (plus outside W3)					
---	--	--	--	--	--

	<u>Targets</u>	<u>Strategies</u>	<u>Outcome</u>	<u>Timeframe</u>	<u>Goals ac</u>
No tactile warnings at the top and bottom of steps - Youngers - DH main staircase - DH staircase near D4 - Back staircase - To Science Labs. - PAC - SH - Watson (plus W3)	Signs clear & understandable for all	Introduce signs	Safer movement around school	2 - 3yrs	Quotes requested

PLATFORM LIFT

Not enough room at top of lift in Sports Hall to manoeuvre - SH	Safer access	Audit & prioritise in future building work	Safer access to Dance Studio	1 - 5yrs	Persons using this are e the door is held open Obtaining prices for au 2017
--	--------------	--	------------------------------	----------	--

WC' S

Fitting not easily distinguished	Fittings easier to	Audit & prioritise in future	Better provision	1 - 3 yrs	
----------------------------------	--------------------	------------------------------	------------------	-----------	--

from background - Youngers - female staff - Youngers - girls - PAC - ladies and gents	distinguish - easier to use facilities	decorating & refurb work			
--	--	--------------------------	--	--	--

	<u>Targets</u>	<u>Strategies</u>	<u>Outcome</u>	<u>Timeframe</u>	<u>Goals ac</u>
No support rails fitted in the cubicles - Youngers - staff - Youngers - girls - PAC - ladies & gents	Improved facility	Will monitor the current situation as it seems to be adequate as the disabled wc's are equipped with support rails	Monitor	Ongoing	

WCS - WHEELCHAIR USERS

Hand washing & drying facilities not within easy reach of someone seated on WC - Youngers - PAC	Improved facility	Audit & prioritise in future building & refurb work	Better provision	1 - 5yrs	
Location not clearly signed - Youngers	Greater accessibility	Introduce signs	Improved accessibility	Ongoing	Quotes sought for DDA compliant signage
No alarm - Youngers	Safer facility	The current situation is adequate but will continue to monitor if this	Safer facility	Ongoing	

- PAC		is acceptable			
-------	--	---------------	--	--	--

INTERNAL SURFACES

	<u>Targets</u>	<u>Strategies</u>	<u>Outcome</u>	<u>Timeframe</u>	<u>Goals ac</u>
Decorative colours and tones not varied to help distinguish between surfaces and fixtures/ittings - General site - PAC	Ease with which to use facilities	Audit & prioritise in future refurb work	Improved facility	1 - 5yrs	
No textured surface to aid orientation for people with impaired sight - General site - PAC	Ease of movement	Audit & prioritise in future refurb work	Improved facility	1 - 5yrs	
Busy or distracting wall coverings - General site	To use the site with ease	Will look at the current situation with the Head of Art & discuss the way forward	Aid to partially sighted	Ongoing	

FACILITIES

No seats provided at intervals on long internal routes	Greater accessibility	Look to incorporate seating on routes through the school	Easier access	1 - 3yrs	
No textphone	Improved facility	Fitted	Improved facility	Complete	
No audible alarms supplemented	Safer site	The current situation is adequate	Safer facility	Ongoing	

by visual alarms		but will continue to monitor the situation			
------------------	--	--	--	--	--

WAYFINDING

	<u>Targets</u>	<u>Strategies</u>	<u>Outcome</u>	<u>Timeframe</u>	<u>Goals ac</u>
Overall layout of building not logical - DH	Improved site	The current situation is adequate as visitors stay with a member of staff. Will look at extra signage.	Improved signage	Ongoing	Quotes sought for DDA compliant signage
Signs not easily identifiable against background - DH	Greater accessibility	Monitor & review the current situation as it is acceptable	Alter signage	Ongoing	Quotes sought for DDA compliant signage
Signs not easy to read - Youngers - DH	Greater accessibility	Monitor & review the current situation as it is acceptable	Alter signage	Ongoing	Quotes sought for DDA compliant signage

ACOUSTICS

No induction loop fitted where info given or meetings held	Greater accessibility	Review, prioritise & program over a 5yr period	Better provision	1 - 5yrs	
--	-----------------------	--	------------------	----------	--

MEANS OF ESCAPE

Alarm system not supplemented by visual system	Safer site	The current situation is adequate but will continue to monitor the situation	Safer facility	Ongoing	
--	------------	--	----------------	---------	--

Ground floor exits not accessible to all, including wheelchair users	Safer exit routes	Audit & prioritise in future building work. Alternative exits are avail to wheelchair users in every building	Safer facility	1 - 5yrs
Vertical escape not possible from upper floor using a fire protected lift with an independent power supply	Safer exit routes	The current provision we have in place is adequate but will continue to monitor the situation	Safer facility	Ongoing

	<u>Targets</u>	<u>Strategies</u>	<u>Outcome</u>	<u>Timeframe</u>	<u>Goals ac</u>
Personal vibratory alarms not provided to employees with hearing impairments	Improved facility	The curretn situation is adequate but will continue to monitor the situation	Improved facility for the hearing impaired	Ongoing	

Updated Spring 2018



AYS




hieved




disabled.

hieved



hieved
om driveway
d out
a disabled space
area for wheel



schedule
8 to

SS

hieved

aces to rear of
w metal framed
cation with

access

tion of new door

glazed with side

visibility panels


ads installed to
l doors with maglocks
(017/18)


hieved

with electronic door
e handed
d exit

x

hieved





hieved

^


^



^

hieved

ads for entry



d to Youngers




hieved





hieved



escorted so
to door opener





hieved



hieved






hieved

^
^
^





hieved

